

Columbia Oldsmobile / Hyundai

I-275 and Montgomery Road
10981 Montgomery Road
Cincinnati, Ohio 45249
(513) 489-2000

HYUNDAI

11/27/2000

Jeffrey Denton was terminated on Monday 11/27
for improper work being done. ON EO # 224283
MR. Treggs stated that all his grease fittings were not
lubed & felt we did not do a proper job. He made a
statement to me that not greasing the joints would
cause premature wear on the parts. Jeffrey has
been cautioned on several occasions to grease all
the fittings when performing a job.

